

PCN Number:	20150901001	PCN Date:	09/08/2015
Title:	Datasheet for LSF0204		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification etc.

The product datasheet(s) is being updated as summarized below.

The following change history provides further details.



LSF0204, LSF0204D

SLVSCP5C – JULY 2014 – REVISED AUGUST 2015

www.ti.com

Changes from Revision April 2015 (B) to Revision C

Page

• Removed "Less than 1.5 ns max propagation delay" from Features.....	1
• Updated "Supports High Speed Translation, Greater Than 100 MHz" bullet in Features.....	1

The datasheet number will be changing.

Device Family	Change From:	Change To:
LSF0204	SLVSCP5B	SLVSCP5C

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/LSF0204>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

LSF0204DPWR	LSF0204DRUTR	LSF0204PWR	LSF0204RUTR
LSF0204DRGYR	LSF0204DYZPR	LSF0204RGYR	LSF0204YZPR

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com