

PCN Number:	20190121001.0	PCN Date:	January 29, 2019
Title:	Datasheet for TS3A5017		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



TS3A5017

SCDS188G – JANUARY 2005 – REVISED JANUARY 2019

Changes from Revision F (October 2018) to Revision G

Page

- Changed *Feature* From: 2000-V Human-Body Model To: 1500-V Human-Body Model 1
- Changed the HBM value From: ± 2000 V To: ± 1500 V in the *ESD Ratings*..... 4

The datasheet number will be changing.

Device Family	Change From:	Change To:
TS3A5017	SCDS188F	SCDS188G

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TS3A5017>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TS3A5017D	TS3A5017DBQR	TS3A5017DGVR	TS3A5017DR
TS3A5017PW	TS3A5017PWG4	TS3A5017PWR	TS3A5017PWRG4
TS3A5017RGYR	TS3A5017RGYRG4	TS3A5017RSVR	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com