

Product Discontinuation Notice


March 2012

Discontinuation of RX and RX-P Relays



1. Reason: Replacement part

2. Affected parts:

RX (ARX) and RX-P (ARXP) relays 	All types	ARX1○ ARXP1○
--	-----------	-----------------

3. Last time buy: End of August 2012

4. Substitution:

RN (ARN) relays (The terminal pitch is different.)	ARN○
--	------

Any questions, please contact your local Panasonic Electric Works Sales representatives.

(Ref#: T-1246-33)