

TAIYO YUDEN

Taiyo Yuden (U.S.A.), Inc.
10 N. Martingale Rd.
Schaumburg, IL 60173
Tel (630) 237-2405 Fax (847) 240-1715
<http://www.t-yuden.com>

Notice of Discontinuation for TAIYO YUDEN (U.S.A.) Inc. Distributors

DATE: March 31st, 2020

RE: Discontinuation of Chip Inductors for High Frequency Applications (HK0402, HKQ0402, HK0603, HKQ0603, HKQ0603W series)

REF NO.: UTY-DN20-01D

TAIYO YUDEN (U.S.A.) Inc. hereby gives notice that the following part series are to be discontinued **3/31/2020** for all TAIYO YUDEN (U.S.A) Inc. distributors. Please note that any last time buys must be made on or before **6/30/2020**. Orders for these components received after the issue date of this notice are Non-Cancelable and Non-Returnable.

Please reference **[Appendix_UTY-DN20-01D_Part List](#)** for the complete list of discontinued parts.

Discontinued Part Series
HK0402_Series
HKQ0402_Series
HK0603_Series
HKQ0603_Series
HKQ0603_Series (□, U, S, C)
HKQ0603W_Series

NOTE: The information in this notice is applicable only to TAIYO YUDEN (U.S.A.) Inc. distribution sales channels. Discontinuation and promotional status changes, change schedules, and availability may vary in other regions. Please contact the TAIYO YUDEN sales office responsible for sales in your country for details on this notice.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department

NotificationPart	Notice Type	Date Issued	LTB Date
HKQ040214NH-E	Discontinuation	3/31/2020	6/30/2020
HKQ040214NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ040214NJ-E	Discontinuation	3/31/2020	6/30/2020
HKQ040214NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ040217NH-E	Discontinuation	3/31/2020	6/30/2020
HKQ040217NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ040217NJ-E	Discontinuation	3/31/2020	6/30/2020
HKQ040217NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ040219NH-E	Discontinuation	3/31/2020	6/30/2020
HKQ040219NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ040219NJ-E	Discontinuation	3/31/2020	6/30/2020
HKQ040219NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ04024N3C-E	Discontinuation	3/31/2020	6/30/2020
HKQ04024N3C-T	Discontinuation	3/31/2020	6/30/2020
HKQ04024N7C-E	Discontinuation	3/31/2020	6/30/2020
HKQ04024N7C-T	Discontinuation	3/31/2020	6/30/2020
HKQ04025N1C-E	Discontinuation	3/31/2020	6/30/2020
HKQ04025N1C-T	Discontinuation	3/31/2020	6/30/2020
HKQ04025N6C-E	Discontinuation	3/31/2020	6/30/2020
HKQ04025N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N5C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N5S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N7C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N7S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N8C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N8S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N9C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S0N9S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S10NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S12NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S15NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S18NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N0C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N0S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N1C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N1S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N2C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N2S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N3C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N3S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N5C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N5S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S1N8S-T	Discontinuation	3/31/2020	6/30/2020

HKQ0402S22NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S27NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S2N0S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S2N2S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S2N4S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S2N7S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S3N0S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S3N3S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S3N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S3N9S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S4N3S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S4N7S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S5N1S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S5N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S6N2J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S6N8J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S7N5J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S8N2J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402S9N1J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N5B-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N5C-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N5S-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N6B-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N6C-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N6S-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N7B-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N7C-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N7S-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N8B-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N8C-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N8S-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N9B-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N9C-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W0N9S-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W10NH-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W10NJ-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W12NH-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W12NJ-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W15NH-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W15NJ-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W18NH-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W18NJ-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W1N0B-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W1N0C-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W1N0S-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W1N1B-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W1N1C-E	Discontinuation	3/31/2020	6/30/2020

HKQ0402W4N7H-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W4N7J-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W4N7S-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W5N1H-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W5N1J-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W5N1S-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W5N6H-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W5N6J-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W5N6S-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W6N2H-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W6N2J-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W6N8H-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W6N8J-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W7N5H-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W7N5J-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W8N2H-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W8N2J-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W9N1H-E	Discontinuation	3/31/2020	6/30/2020
HKQ0402W9N1J-E	Discontinuation	3/31/2020	6/30/2020
HK060310NG-T	Discontinuation	3/31/2020	6/30/2020
HK060310NG-TA	Discontinuation	3/31/2020	6/30/2020
HK060310NH-T	Discontinuation	3/31/2020	6/30/2020
HK060310NH-TA	Discontinuation	3/31/2020	6/30/2020
HK060310NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060310NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060310NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060310NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060310NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK060310NJ-TZ	Discontinuation	3/31/2020	6/30/2020
HK060310NJZT	Discontinuation	3/31/2020	6/30/2020
HK060312NG-T	Discontinuation	3/31/2020	6/30/2020
HK060312NH-T	Discontinuation	3/31/2020	6/30/2020
HK060312NH-TA	Discontinuation	3/31/2020	6/30/2020
HK060312NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060312NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060312NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060312NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060312NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK060312NJ-TZ	Discontinuation	3/31/2020	6/30/2020
HK060315NG-T	Discontinuation	3/31/2020	6/30/2020
HK060315NH-T	Discontinuation	3/31/2020	6/30/2020
HK060315NH-TA	Discontinuation	3/31/2020	6/30/2020
HK060315NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060315NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060315NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060315NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060315NJ-TV	Discontinuation	3/31/2020	6/30/2020

HK060315NJ-TZ	Discontinuation	3/31/2020	6/30/2020
HK060318NG-T	Discontinuation	3/31/2020	6/30/2020
HK060318NH-T	Discontinuation	3/31/2020	6/30/2020
HK060318NH-TA	Discontinuation	3/31/2020	6/30/2020
HK060318NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060318NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060318NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060318NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060318NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK060318NJ-TZ	Discontinuation	3/31/2020	6/30/2020
HK06031NOC-T	Discontinuation	3/31/2020	6/30/2020
HK06031NOC-TA	Discontinuation	3/31/2020	6/30/2020
HK06031NOS-T	Discontinuation	3/31/2020	6/30/2020
HK06031NOS-T.	Discontinuation	3/31/2020	6/30/2020
HK06031NOS-TA	Discontinuation	3/31/2020	6/30/2020
HK06031NOS-TL	Discontinuation	3/31/2020	6/30/2020
HK06031NOS-TV	Discontinuation	3/31/2020	6/30/2020
HK06031N1C-T	Discontinuation	3/31/2020	6/30/2020
HK06031N1S-T	Discontinuation	3/31/2020	6/30/2020
HK06031N1S-TL	Discontinuation	3/31/2020	6/30/2020
HK06031N2C-T	Discontinuation	3/31/2020	6/30/2020
HK06031N2C-TV	Discontinuation	3/31/2020	6/30/2020
HK06031N2S-T	Discontinuation	3/31/2020	6/30/2020
HK06031N2S-T.	Discontinuation	3/31/2020	6/30/2020
HK06031N2S-TA	Discontinuation	3/31/2020	6/30/2020
HK06031N2S-TL	Discontinuation	3/31/2020	6/30/2020
HK06031N2S-TV	Discontinuation	3/31/2020	6/30/2020
HK06031N2S-TZ	Discontinuation	3/31/2020	6/30/2020
HK06031N3C-T	Discontinuation	3/31/2020	6/30/2020
HK06031N3S-T	Discontinuation	3/31/2020	6/30/2020
HK06031N3S-TL	Discontinuation	3/31/2020	6/30/2020
HK06031N5C-T	Discontinuation	3/31/2020	6/30/2020
HK06031N5C-TA	Discontinuation	3/31/2020	6/30/2020
HK06031N5S-T	Discontinuation	3/31/2020	6/30/2020
HK06031N5S-T.	Discontinuation	3/31/2020	6/30/2020
HK06031N5S-TA	Discontinuation	3/31/2020	6/30/2020
HK06031N5S-TL	Discontinuation	3/31/2020	6/30/2020
HK06031N5S-TV	Discontinuation	3/31/2020	6/30/2020
HK06031N6C-T	Discontinuation	3/31/2020	6/30/2020
HK06031N6S-T	Discontinuation	3/31/2020	6/30/2020
HK06031N6S-TL	Discontinuation	3/31/2020	6/30/2020
HK06031N8C-T	Discontinuation	3/31/2020	6/30/2020
HK06031N8C-TA	Discontinuation	3/31/2020	6/30/2020
HK06031N8S-T	Discontinuation	3/31/2020	6/30/2020
HK06031N8S-T.	Discontinuation	3/31/2020	6/30/2020
HK06031N8S-TA	Discontinuation	3/31/2020	6/30/2020
HK06031N8S-TL	Discontinuation	3/31/2020	6/30/2020

HK06031N8S-TV	Discontinuation	3/31/2020	6/30/2020
HK06031N8S-TZ	Discontinuation	3/31/2020	6/30/2020
HK060322NG-T	Discontinuation	3/31/2020	6/30/2020
HK060322NH-T	Discontinuation	3/31/2020	6/30/2020
HK060322NH-TA	Discontinuation	3/31/2020	6/30/2020
HK060322NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060322NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060322NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060322NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060322NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK060327NG-T	Discontinuation	3/31/2020	6/30/2020
HK060327NH-T	Discontinuation	3/31/2020	6/30/2020
HK060327NH-TV	Discontinuation	3/31/2020	6/30/2020
HK060327NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060327NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060327NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060327NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060327NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK060327NJ-TZ	Discontinuation	3/31/2020	6/30/2020
HK06032N0C-T	Discontinuation	3/31/2020	6/30/2020
HK06032N0C-TA	Discontinuation	3/31/2020	6/30/2020
HK06032N0S-T	Discontinuation	3/31/2020	6/30/2020
HK06032N0S-TA	Discontinuation	3/31/2020	6/30/2020
HK06032N0S-TL	Discontinuation	3/31/2020	6/30/2020
HK06032N0S-TV	Discontinuation	3/31/2020	6/30/2020
HK06032N2C-T	Discontinuation	3/31/2020	6/30/2020
HK06032N2C-TA	Discontinuation	3/31/2020	6/30/2020
HK06032N2C-TV	Discontinuation	3/31/2020	6/30/2020
HK06032N2S-T	Discontinuation	3/31/2020	6/30/2020
HK06032N2S-T.	Discontinuation	3/31/2020	6/30/2020
HK06032N2S-TA	Discontinuation	3/31/2020	6/30/2020
HK06032N2S-TL	Discontinuation	3/31/2020	6/30/2020
HK06032N2S-TV	Discontinuation	3/31/2020	6/30/2020
HK06032N4C-T	Discontinuation	3/31/2020	6/30/2020
HK06032N4C-TA	Discontinuation	3/31/2020	6/30/2020
HK06032N4S-T	Discontinuation	3/31/2020	6/30/2020
HK06032N4S-TA	Discontinuation	3/31/2020	6/30/2020
HK06032N4S-TL	Discontinuation	3/31/2020	6/30/2020
HK06032N4S-TV	Discontinuation	3/31/2020	6/30/2020
HK06032N7C-T	Discontinuation	3/31/2020	6/30/2020
HK06032N7C-TA	Discontinuation	3/31/2020	6/30/2020
HK06032N7S-T	Discontinuation	3/31/2020	6/30/2020
HK06032N7S-T.	Discontinuation	3/31/2020	6/30/2020
HK06032N7S-TA	Discontinuation	3/31/2020	6/30/2020
HK06032N7S-TL	Discontinuation	3/31/2020	6/30/2020
HK06032N7S-TV	Discontinuation	3/31/2020	6/30/2020
HK060333NG-T	Discontinuation	3/31/2020	6/30/2020

HK060333NH-T	Discontinuation	3/31/2020	6/30/2020
HK060333NH-TV	Discontinuation	3/31/2020	6/30/2020
HK060333NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060333NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060333NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060333NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060333NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK060339NG-T	Discontinuation	3/31/2020	6/30/2020
HK060339NH-T	Discontinuation	3/31/2020	6/30/2020
HK060339NH-TA	Discontinuation	3/31/2020	6/30/2020
HK060339NH-TV	Discontinuation	3/31/2020	6/30/2020
HK060339NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060339NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060339NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060339NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060339NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK06033NOC-T	Discontinuation	3/31/2020	6/30/2020
HK06033NOC-TA	Discontinuation	3/31/2020	6/30/2020
HK06033NOS-T	Discontinuation	3/31/2020	6/30/2020
HK06033NOS-TA	Discontinuation	3/31/2020	6/30/2020
HK06033NOS-TL	Discontinuation	3/31/2020	6/30/2020
HK06033NOS-TV	Discontinuation	3/31/2020	6/30/2020
HK06033NOS-TY	Discontinuation	3/31/2020	6/30/2020
HK06033N3C-T	Discontinuation	3/31/2020	6/30/2020
HK06033N3C-TA	Discontinuation	3/31/2020	6/30/2020
HK06033N3C-TV	Discontinuation	3/31/2020	6/30/2020
HK06033N3S-T	Discontinuation	3/31/2020	6/30/2020
HK06033N3S-T.	Discontinuation	3/31/2020	6/30/2020
HK06033N3S-TA	Discontinuation	3/31/2020	6/30/2020
HK06033N3S-TL	Discontinuation	3/31/2020	6/30/2020
HK06033N3S-TV	Discontinuation	3/31/2020	6/30/2020
HK06033N3S-TZ	Discontinuation	3/31/2020	6/30/2020
HK06033N6C-T	Discontinuation	3/31/2020	6/30/2020
HK06033N6C-TA	Discontinuation	3/31/2020	6/30/2020
HK06033N6S-T	Discontinuation	3/31/2020	6/30/2020
HK06033N6S-TA	Discontinuation	3/31/2020	6/30/2020
HK06033N6S-TL	Discontinuation	3/31/2020	6/30/2020
HK06033N6S-TV	Discontinuation	3/31/2020	6/30/2020
HK06033N9C-T	Discontinuation	3/31/2020	6/30/2020
HK06033N9C-TA	Discontinuation	3/31/2020	6/30/2020
HK06033N9C-TV	Discontinuation	3/31/2020	6/30/2020
HK06033N9S-T	Discontinuation	3/31/2020	6/30/2020
HK06033N9S-T.	Discontinuation	3/31/2020	6/30/2020
HK06033N9S-TA	Discontinuation	3/31/2020	6/30/2020
HK06033N9S-TL	Discontinuation	3/31/2020	6/30/2020
HK06033N9S-TV	Discontinuation	3/31/2020	6/30/2020
HK060347NG-T	Discontinuation	3/31/2020	6/30/2020

HK060347NH-T	Discontinuation	3/31/2020	6/30/2020
HK060347NH-TV	Discontinuation	3/31/2020	6/30/2020
HK060347NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060347NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060347NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060347NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060347NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK060347NJ-TZ	Discontinuation	3/31/2020	6/30/2020
HK06034N3C-T	Discontinuation	3/31/2020	6/30/2020
HK06034N3C-TA	Discontinuation	3/31/2020	6/30/2020
HK06034N3S-T	Discontinuation	3/31/2020	6/30/2020
HK06034N3S-TA	Discontinuation	3/31/2020	6/30/2020
HK06034N3S-TL	Discontinuation	3/31/2020	6/30/2020
HK06034N3S-TV	Discontinuation	3/31/2020	6/30/2020
HK06034N7C-T	Discontinuation	3/31/2020	6/30/2020
HK06034N7C-TA	Discontinuation	3/31/2020	6/30/2020
HK06034N7S-T	Discontinuation	3/31/2020	6/30/2020
HK06034N7S-T.	Discontinuation	3/31/2020	6/30/2020
HK06034N7S-TA	Discontinuation	3/31/2020	6/30/2020
HK06034N7S-TL	Discontinuation	3/31/2020	6/30/2020
HK06034N7S-TV	Discontinuation	3/31/2020	6/30/2020
HK06034N7S-TZ	Discontinuation	3/31/2020	6/30/2020
HK060356NG-T	Discontinuation	3/31/2020	6/30/2020
HK060356NH-T	Discontinuation	3/31/2020	6/30/2020
HK060356NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060356NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060356NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060356NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060356NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK06035N1C-T	Discontinuation	3/31/2020	6/30/2020
HK06035N1C-TA	Discontinuation	3/31/2020	6/30/2020
HK06035N1S-T	Discontinuation	3/31/2020	6/30/2020
HK06035N1S-TA	Discontinuation	3/31/2020	6/30/2020
HK06035N1S-TL	Discontinuation	3/31/2020	6/30/2020
HK06035N1S-TV	Discontinuation	3/31/2020	6/30/2020
HK06035N6C-T	Discontinuation	3/31/2020	6/30/2020
HK06035N6C-TA	Discontinuation	3/31/2020	6/30/2020
HK06035N6J-T	Discontinuation	3/31/2020	6/30/2020
HK06035N6S-T	Discontinuation	3/31/2020	6/30/2020
HK06035N6S-T.	Discontinuation	3/31/2020	6/30/2020
HK06035N6S-TA	Discontinuation	3/31/2020	6/30/2020
HK06035N6S-TL	Discontinuation	3/31/2020	6/30/2020
HK06035N6S-TV	Discontinuation	3/31/2020	6/30/2020
HK060368NG-T	Discontinuation	3/31/2020	6/30/2020
HK060368NH-T	Discontinuation	3/31/2020	6/30/2020
HK060368NH-TV	Discontinuation	3/31/2020	6/30/2020
HK060368NJ-T	Discontinuation	3/31/2020	6/30/2020

HK060368NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060368NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060368NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060368NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK060368NJ-TZ	Discontinuation	3/31/2020	6/30/2020
HK06036N2C-T	Discontinuation	3/31/2020	6/30/2020
HK06036N2C-TV	Discontinuation	3/31/2020	6/30/2020
HK06036N2S-T	Discontinuation	3/31/2020	6/30/2020
HK06036N2S-TA	Discontinuation	3/31/2020	6/30/2020
HK06036N2S-TL	Discontinuation	3/31/2020	6/30/2020
HK06036N2S-TV	Discontinuation	3/31/2020	6/30/2020
HK06036N2S-TZ	Discontinuation	3/31/2020	6/30/2020
HK06036N8G-T	Discontinuation	3/31/2020	6/30/2020
HK06036N8H-T	Discontinuation	3/31/2020	6/30/2020
HK06036N8H-TA	Discontinuation	3/31/2020	6/30/2020
HK06036N8J-T	Discontinuation	3/31/2020	6/30/2020
HK06036N8J-T.	Discontinuation	3/31/2020	6/30/2020
HK06036N8J-TA	Discontinuation	3/31/2020	6/30/2020
HK06036N8J-TL	Discontinuation	3/31/2020	6/30/2020
HK06036N8J-TV	Discontinuation	3/31/2020	6/30/2020
HK06036N8J-TZ	Discontinuation	3/31/2020	6/30/2020
HK06037N5G-T	Discontinuation	3/31/2020	6/30/2020
HK06037N5H-T	Discontinuation	3/31/2020	6/30/2020
HK06037N5H-TA	Discontinuation	3/31/2020	6/30/2020
HK06037N5J-T	Discontinuation	3/31/2020	6/30/2020
HK06037N5J-TA	Discontinuation	3/31/2020	6/30/2020
HK06037N5J-TL	Discontinuation	3/31/2020	6/30/2020
HK06037N5J-TV	Discontinuation	3/31/2020	6/30/2020
HK060382NG-T	Discontinuation	3/31/2020	6/30/2020
HK060382NH-T	Discontinuation	3/31/2020	6/30/2020
HK060382NJ-T	Discontinuation	3/31/2020	6/30/2020
HK060382NJ-T.	Discontinuation	3/31/2020	6/30/2020
HK060382NJ-TA	Discontinuation	3/31/2020	6/30/2020
HK060382NJ-TL	Discontinuation	3/31/2020	6/30/2020
HK060382NJ-TV	Discontinuation	3/31/2020	6/30/2020
HK06038N2G-T	Discontinuation	3/31/2020	6/30/2020
HK06038N2G-TA	Discontinuation	3/31/2020	6/30/2020
HK06038N2H-T	Discontinuation	3/31/2020	6/30/2020
HK06038N2J-T	Discontinuation	3/31/2020	6/30/2020
HK06038N2J-T.	Discontinuation	3/31/2020	6/30/2020
HK06038N2J-TA	Discontinuation	3/31/2020	6/30/2020
HK06038N2J-TL	Discontinuation	3/31/2020	6/30/2020
HK06038N2J-TV	Discontinuation	3/31/2020	6/30/2020
HK06038N2J-TZ	Discontinuation	3/31/2020	6/30/2020
HK060391NH-T	Discontinuation	3/31/2020	6/30/2020
HK060391NJ-T	Discontinuation	3/31/2020	6/30/2020
HK06039N1G-T	Discontinuation	3/31/2020	6/30/2020

HK06039N1H-T	Discontinuation	3/31/2020	6/30/2020
HK06039N1J-T	Discontinuation	3/31/2020	6/30/2020
HK06039N1J-TA	Discontinuation	3/31/2020	6/30/2020
HK06039N1J-TL	Discontinuation	3/31/2020	6/30/2020
HK06039N1J-TV	Discontinuation	3/31/2020	6/30/2020
HK0603R10G-T	Discontinuation	3/31/2020	6/30/2020
HK0603R10H-T	Discontinuation	3/31/2020	6/30/2020
HK0603R10H-TV	Discontinuation	3/31/2020	6/30/2020
HK0603R10J-T	Discontinuation	3/31/2020	6/30/2020
HK0603R10J-T.	Discontinuation	3/31/2020	6/30/2020
HK0603R10J-TA	Discontinuation	3/31/2020	6/30/2020
HK0603R10J-TL	Discontinuation	3/31/2020	6/30/2020
HK0603R10J-TV	Discontinuation	3/31/2020	6/30/2020
HK0603R10J-TZ	Discontinuation	3/31/2020	6/30/2020
HKQ06030N6B-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N7B-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N7C-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N7S-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N8B-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N8C-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N8S-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N9B-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N9C-T	Discontinuation	3/31/2020	6/30/2020
HKQ06030N9S-T	Discontinuation	3/31/2020	6/30/2020
HKQ060310NG-T	Discontinuation	3/31/2020	6/30/2020
HKQ060310NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ060310NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ060312NG-T	Discontinuation	3/31/2020	6/30/2020
HKQ060312NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ060312NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ060315NG-T	Discontinuation	3/31/2020	6/30/2020
HKQ060315NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ060315NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ060318NG-T	Discontinuation	3/31/2020	6/30/2020
HKQ060318NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ060318NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ06031N0B-T	Discontinuation	3/31/2020	6/30/2020
HKQ06031N0C-T	Discontinuation	3/31/2020	6/30/2020
HKQ06031N0S-T	Discontinuation	3/31/2020	6/30/2020
HKQ06031N1B-T	Discontinuation	3/31/2020	6/30/2020
HKQ06031N1C-T	Discontinuation	3/31/2020	6/30/2020
HKQ06031N1S-T	Discontinuation	3/31/2020	6/30/2020
HKQ06031N2B-T	Discontinuation	3/31/2020	6/30/2020
HKQ06031N2C-T	Discontinuation	3/31/2020	6/30/2020
HKQ06031N2S-T	Discontinuation	3/31/2020	6/30/2020

HKQ06035N1S-T	Discontinuation	3/31/2020	6/30/2020
HKQ06035N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ06035N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ06036N2C-T	Discontinuation	3/31/2020	6/30/2020
HKQ06036N2S-T	Discontinuation	3/31/2020	6/30/2020
HKQ06036N8H-T	Discontinuation	3/31/2020	6/30/2020
HKQ06036N8J-T	Discontinuation	3/31/2020	6/30/2020
HKQ06037N5H-T	Discontinuation	3/31/2020	6/30/2020
HKQ06037N5J-T	Discontinuation	3/31/2020	6/30/2020
HKQ06038N2H-T	Discontinuation	3/31/2020	6/30/2020
HKQ06038N2J-T	Discontinuation	3/31/2020	6/30/2020
HKQ06039N1H-T	Discontinuation	3/31/2020	6/30/2020
HKQ06039N1J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N6B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N7B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N7C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N7S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N8B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N8C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N8S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N9B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N9C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C0N9S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C10NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C10NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C12NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C12NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C15NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C15NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C18NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C18NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N0B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N0C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N0S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N1B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N1C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N1S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N2B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N2C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N2S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N3B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N3C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N3S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N4B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C1N4C-T	Discontinuation	3/31/2020	6/30/2020

HKQ0603C6N8J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C7N5H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C7N5J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C8N2H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C8N2J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C9N1H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603C9N1J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S0N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S0N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S0N7C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S0N7S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S0N8C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S0N8S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S0N9C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S0N9S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S10NG-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S10NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S10NH-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S10NH-TV	Discontinuation	3/31/2020	6/30/2020
HKQ0603S10NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S10NJ-TV	Discontinuation	3/31/2020	6/30/2020
HKQ0603S12NG-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S12NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S12NH-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S12NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S15NG-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S15NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S15NH-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S15NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S15NJ-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S18NG-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S18NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S18NH-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S18NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N0B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N0B-TZ	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N0C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N0S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N1C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N1S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N2C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N2S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N3C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N3S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N4C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N4S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S1N5C-T	Discontinuation	3/31/2020	6/30/2020

HKQ0603S3N4S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N5C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N5S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N6B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N6C-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N7C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N7S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N8C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N8S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N9C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S3N9S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S4N3C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S4N3S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S4N7C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S4N7C-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S4N7S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S5N1C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S5N1C-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S5N1S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S5N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S5N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S5N6S-TV	Discontinuation	3/31/2020	6/30/2020
HKQ0603S6N2C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S6N2C-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S6N2S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S6N8H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S6N8H-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S6N8J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S7N5H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S7N5H-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S7N5H-TZ	Discontinuation	3/31/2020	6/30/2020
HKQ0603S7N5J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S8N2H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S8N2H-T.	Discontinuation	3/31/2020	6/30/2020
HKQ0603S8N2J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S9N1H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603S9N1J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603U0N6B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603U0N6B-TV	Discontinuation	3/31/2020	6/30/2020
HKQ0603U0N6B-TX	Discontinuation	3/31/2020	6/30/2020
HKQ0603U0N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603U0N6C-TV	Discontinuation	3/31/2020	6/30/2020
HKQ0603U0N6C-TX	Discontinuation	3/31/2020	6/30/2020
HKQ0603U0N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603U0N6S-TV	Discontinuation	3/31/2020	6/30/2020

HKQ0603W1N5C-TK	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N5C-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N5S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N5S-TK	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N5S-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N6B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N6B-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N6C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N6C-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N6S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N6S-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N7B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N7B-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N7C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N7C-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N7S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N7S-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N8B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N8B-TK	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N8B-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N8C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N8C-TK	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N8C-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N8S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N8S-TK	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N8S-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N9B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N9B-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N9C-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N9C-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N9S-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W1N9S-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W20NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W20NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W22NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W22NH-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W22NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W22NJ-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W24NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W24NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W27NH-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W27NH-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W27NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W27NJ-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W2N0B-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W2N0B-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W2N0C-T	Discontinuation	3/31/2020	6/30/2020

HKQ0603W6N8H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W6N8H-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W6N8J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W6N8J-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W7N5H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W7N5H-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W7N5J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W7N5J-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W82NJ-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W82NJ-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W8N2H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W8N2H-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W8N2H-ZT	Discontinuation	3/31/2020	6/30/2020
HKQ0603W8N2J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W8N2J-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W9N1H-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W9N1H-TK	Discontinuation	3/31/2020	6/30/2020
HKQ0603W9N1H-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603W9N1J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603W9N1J-TK	Discontinuation	3/31/2020	6/30/2020
HKQ0603W9N1J-TM	Discontinuation	3/31/2020	6/30/2020
HKQ0603WR10J-T	Discontinuation	3/31/2020	6/30/2020
HKQ0603WR10J-TM	Discontinuation	3/31/2020	6/30/2020

Notes