



EOL-238005

Product Obsolescence Notification

Issue Date: September 23, 2021

Dear Customer:

Broadcom regrets to announce the immediate obsolescence of the following products, as Broadcom's wafer supplier is discontinuing the manufacture of wafers for these products. Broadcom will not be able to accept any new orders under the obsoleted part numbers.

Broadcom Part Numbers	Description
BCM53724B0KPBG	24p GE+2x1G Switch
BCM53726B0KPBG	16p GE+2x1G Switch
BCM56024B0IPBG	24 PORT FE MULTI LAYER SWITCH
BCM56024B0KPBG	24 PORT FE MULTI LAYER SWITCH
BCM56025B0IPBG	24 PORT FE MULTI LAYER SWITCH
BCM56025B0KPBG	24 PORT FE MULTI LAYER SWITCH
BCM56026B0IPBG	24 PORT FE MULTI LAYER SWITCH
BCM56026B0KPBG	24 PORT FE MULTI LAYER SWITCH
BCM56224B0IPBG	24p GE+4x1G/2.5G Switch, I-Temp
BCM56224B0KPBG	24p GE+4x1G/2.5G Switch
BCM56226B0IPBG	16p GE+4x1G/2.5G Switch, I-Temp
BCM56226B0KPBG	16p GE+4x1G/2.5G Switch
BCM56228B0IPBG	8p GE+4x1G/2.5G Switch, I-Temp
BCM56228B0KPBG	8p GE+4x1G/2.5G Switch
BCM56229B0IPBG	8p GE+4x1G/2.5G L2 Switch, I-Temp
BCM56229B0KPBG	8p GE+4x1G/2.5G L2 Switch

Please contact your Broadcom Sales Representative for questions or concerns.

Please contact your Broadcom Field Sales Engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.